

venue, Maywood, IL 60453 } ; } Illinois Environmental P

DATE:

March 29, 1993

TO:

Sy Levine

FROM:

David C. Beener

Last Insp. Date:

Date of Inspection:

January 14, 1993

March 18, 1993

708/531-5900

Region/District:

1-01

Facility:

Abandoned Wyman-Gdrdon Bidg.

I.D. #:

Phone:

031 111 AAF

Address:

14600 S. Hood St..

Harvey, IL 60426

215/434-8656

Contact/Title: Michael Owens of: Harvey GRQ Ind.

1 West Ave. Larchmont, NY | 10538

815/933-2554

Christopher Curtis of: Glerczyk Development

RECEIVED DIVISION OF LEGAL COUNSEL

EPA Region 5 Records Ctr.



230194

7.1 0 **8** 1993

ENVIRONMENTAL PHOTECTION AGENCY

March 18, 1993 by D. Beener Author met with the following individuals at 12:30 p.m. at facility property:

> Christopher Curtis/Real Estate agent for Gierczyk Development Jerry Graff/Contractor-Consultant for Harvey GRQ

The purpose of inspection was to identify the various problem areas throughout the property and familiarize Mr. Graff with the current condition of the property. Mr. Graff is an associate of Mr. Tom Bopp/Consultant for Harvey GRQ and has been enlisted to provide an assessment of current conditions, relay to secure property. steps to secure property.

A walk-through was performed of all buildings west of Hood Street where sampling has been performed by both USEPA and IEPA offices. Initially addressed were buildings A, B. D. E. G, I, K and L through S, as these are the most readily accessible to the public. Of particular concern is building Q where a new tenant has recently (March), 1993) signed a lease. The bay in question has friable asbestos material (20-30% Crocidolite) in poor condition on pipe and deposits on ground within the area. The author agreed with Mr. Graff that this was an immediate health related concern and Mr. Graff indicated that this was an area that should receive a high priority. Significant quantities of friable asbestos materials are located throughout the buildings. Mr. Graff felt that installing chain-link fences might be a reasonable alternative to securing the access to buildings as an initial step. plywood/sheeting and constructing present doors and constructing

NFR 2 6 1993 Division Region II well



Section I of Two Sections Summary

Analyst's Approval : []

Client: IL Environmental Protection Agency Report Number: 93-01-00293

	TEST	RE	POR	T
--	------	----	-----	---

RIDG "G"

		TEST REPORT DLUG G
ITL	Number	Sample Identification
	90883	1-a, 1/14/93, Tire Bldg. Floor Beneath Pipes Asbestos, Chrysotile Mica Diatoms Unspecified Non-Fibrous Mat'l 40-50%
	90884	1-b, 1/14/93, Rear of Tire Bldg Ground Beneath Pipes Asbestos, Chrysotile Mica Unspecified Non-Fibrous Mat'l 40-50%
	90885	1-c, 1/14/93, Adjacent To Tire Bldg Floor Beneath Pipes Asbestos, Chrysotile Mica Unspecified Non-Fibrous Mat'l 40-50%



Section I of Two Sections

Summary

Analyst's Approval : [55]

Client: IL Environmental Protection Agency Report Number: 93-03-01052

TEST REPORT

T	L Number	Sample Identification
	94520	Sample 1-B (Lab #259), 3-2-93, Floor Of Bldg. G, Beneath Overhead Pipes
		Asbestos, Chrysotile 20-30%
		Mineral Wool Trace
		Perlite 3-5%
		Mica 20-30%
		Unspecified Non-Fibrous Mat 1 30-40%
	94521	Sample 2-B (Lab #260), 3-2-93, Floor Of Bldg. F, Sign Indicated Bldg. C on Exterior Beneath Pipes
١		Ambestom, Crocidolite 20-30%
١		Cellulose 1-3%
Ì		Mineral Wool 3-5%
1		Diatoms 5-10%
		Unspecified Non-Fibrous Mat 1 50-60%
	94522	Sample 3-B (Lab #261), 3-2-93, Floor Of Bldg. A, Beneath Overhead Pipes
1		Asbestos, Chrysotile 20-30%
j		Mineral Wool 1-3%
١		Mica 20-30%
ļ		Unspecified Non-Fibrous Mat'l 40-50%